Public Footpaths Nos 17 and 57 Ely – Network Rail TTRO Application - Problems with alternative routes

Padnal Bank (FP17 Ely)

Photo 1 View from south showing high steep, vegetated bank (Streetview 2011)

Photo 2 Close-up of steep bank adjacent to bridge; evidence of use

(CCC 21.10.2016)

Photo 3 and 4: View from north showing high steep bank, barbed wire obstruction, no safe verge refuge, and slippery mud on road edge (CCC 21.10.2016)

Photo 5: Example of Environment Agency steps in bank (CCC 21.10.2016)

Photo 6: Example of Network Rail steps in bank (CCC 21.10.2016)

Branch Bank FP57 Ely

Photo 7 View from south showing high steep, vegetated bank (Streetview 2011)

Photo 8: Randomly located unofficial sign – what are walkers supposed to do? (CCC 21.10.2016)

Photo 9 View from north showing high, steep vegetated bank and barbed wire obstruction beside road (Streetview 2011)

Photo 10: Worn route through stinging nettles adjacent to railway bridge; landowner's barbed wire fence has been broken down

(CCC 21.10.2016)