C18 Munceys, Fordham

Site Photographs 13th October 2017

Existing route 1

Photo 1 – Eastern approach to C18

Photo 2 – vegetation at C18

Photo 3 – FP19 at C18

Photo 4 – narrow path on West side of C18

Photo 6 – Western approach to C18

Photo 7 – Western approach to C18 looking west

Photo 8 – FP 19

Photo 9 – alternative route

Photo 10 – poor visibility and limited road space on alternative route

Photo 11 - poor visibility and limited road space on alternative route

Photo 12 – limited accessibility adjacent road bridge

Photo 13 – very narrow verge at road bridge on alternative route