

Appendix 1 – Adelaide Level Crossing showing absence of decking



Photo 1 - FP49 Stile looking east up railway embankment to crossing (King's Lynn line)



Photo 2 - Detail of stile



Photo 3 - Looking East over level crossing – no decking



Looking west back along FP49 from crossing